



木

報告編號:KB-11-04200ZA C-11-10291

1 OF 報告日期:100年 05月 05日

試驗報告

名機 稱關 商:

單廠名部 位: 商:

位:

取送取收試試 樣驗樣件驗

人日

日日 期: 期:

試驗結果:

測試項目	樣品編號	測試結果	CNS 2217(1985)規範要求
耐衝擊性	1 號	無破壞	
	2 號	無破壞	
	3 號	無破壞	
	4 號	無破壞	
	5 號	無破壞	
	6 號	無破壞	
破碎試驗(塊)	7號	67.5	一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一 一
	8 號	71.0	
	9 號	68.5	
	10 號	66.5	
	11 號	70.5	

本報告若有提供規範值時,該規範值僅供參考,合格之判定以委託單位實際要求為準

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責。本報告未經本公司書面許可,不可部份複製。

This Test Report is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this Test Report is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

TWA 0660565

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司

No.61, Kai -Fa Road, Nanzih Export Processing Zone, Kaohsiung, Taiwan /高雄市楠梓加工出口區開發路61號 t (886-7) 301-2121 f (886-7) 301-1276 www.tw.sgs.com